

KING COUNTY INTERNATIONAL AIRPORT INCIDENT REPORT

INCIDENT:
FUEL SPILL

DATE OCC:
TIME OCC:

DATE REPTD: 6/27/98
TIME REPTD: 1304

LOCATION(S) OF OCCURRENCE:

GUARDIAN I RAMP

REPORTED BY:

PHONE NO(S):

LISA AT TOWER

SUMMARY:

REPORT OF A FUEL LEAK COMING FROM A FUEL TRUCK AT ABOVE LOCATION.
OFC. MATTISON RESPONDED AND FOUND A 10' X 10' JET A FUEL SPILL COMING FROM THE GUARDIAN I FUEL TRUCK (WA LIC: 34888C). FUEL LEAK WAS DUE TO HEAT EXPANSION AND WAS COMING OUT OF HOSE/NOZZLE WHICH IS STORED ON DRIVERS SIDE OF THE MILITARY STYLE FUEL VEHICLE.
OFC. CHRISTENSON CALLED SHERIFF COMMUNICATIONS, OPR #51 AND REQUESTED A GUARDIAN I PERSONNEL TO RESPONDED TO SCENE.
1315 - SCOTTY, PILOT OF GUARDIAN ONE CALLED AND ADVISED HE WAS EN ROUTE, ETA 30-40 MIN.
OFC. MATTISON PUT DOWN 2-SMALL BOOMS, 1-PILLOW AND 10-12"X 12" PADS ON THE FUEL SPILL.
1415 - SGT EADES ADVISED THAT HE OBSERVED GUARDIAN I PERSONNEL AT LOCATION HANDLING THE REST OF THE CLEANUP.

OFFICERS: B. CHRISTENSON

ACTION: CPL. DICKIE